DOCKET NO.: 331957US-6SD

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

IN RE APPLICATION OF: JEAN-PAUL ARTIS ET AL.

PATENT NO.: 7,000,722 GROUP: 3618

ISSUED: FEBRUARY 21, 2006 EXAMINER: AVERY, B.

FOR: OPERATING DEVICE FOR A CRUISE CONTROL SYSTEM OF AN

AUTOMOBILE VEHICLE

REQUEST FOR CERTIFICATE OF CORRECTION

DIRECTOR OF THE UNITED STATES PATENT AND TRADEMARK OFFICE ALEXANDRIA, VA 22313-1450

SIR:

The following is a Request for Certificate of Correction in Serial Number 10/626,689, now U.S. Patent Number 7,000,722.

In accordance with the provisions of Rule 322 of the Rules of Practice, which implement 35 USC 255, the U.S. Patent and Trademark Office is respectfully requested to issue a Certificate of Correction in the above-identified patent.

In light of the fact that the errors were the fault of our office, the required fee of \$100 is enclosed. The requested corrections are listed on FORM P.T.O. 1050.

Respectfully submitted,

OBLON, SPIVAK, McCLELLAND, MAIER & NEUSTADT, P.C.

Gregory J. Maier

Registration No. 25,599

Customer Number

22850

Tel. (703) 413-3000 Fax. (703) 413-2220 (OSMMN 07/08) Surinder Sachar

Registration No. 34,423

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.:

7,000,722

DATED:

pedal--.

FEBRUARY 21, 2006

INVENTOR(S):

JEAN-PAUL ARTIS ET AL.

It is certified that an error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 3, line 58, change "depresses the brake pedal" to --depresses the accelerator pedal--;

line 64, change "depresses the brake pedal" to --depresses the accelerator

Mailing address of sender:

Patent No.

7,000,722

Customer Number

No. of add'l copies @ .30 per page

22850

Tel. (703) 413-3000 Fax. (703) 413-2220 (OSMMN 03/02)